

Lump, Ryerson & Association  
14747 California St.  
Omaha NE 68154-1952

BOOK 1053 PAGE 734

**AFFIDAVIT OF CORRECTION**

DIAMOND HEAD, a subdivision, as surveyed, platted and recorded in Douglas County, Nebraska. The dimension tie between the southeast corner of Lot 239 and the SW Corner of the SW 1/4 of Section 11, T15N, R11E, Douglas County, Nebraska should be 2388.49 feet instead of 2288.49 AND the dimension tie between the northwest corner of Lot 215 and the NW Corner of the SW 1/4 of Section 11, T15N, R11E, Douglas County, Nebraska, should be 609.00 feet instead of 554.00 feet.

A-F-F-I-D-A-V-I-T

Correction to DIAMOND HEAD, a subdivision, as surveyed, platted and recorded in Douglas County, Nebraska.

I, Robert D. Proett, do submit this affidavit in order to correct a drafting error in the Final Plat of DIAMOND HEAD as recorded on December 27, 1991 in Book 1914, page 148 in the Register of Deeds office in Douglas County, Nebraska.

I hereby certify that I am the identical person whose name appears on the Surveyor's Certificate of said DIAMOND HEAD

Robert D. Proett, L.S. # 3799

STATE OF NEBRASKA)  
COUNTY OF DOUGLAS)

On this 24th day of December, 1992, before me a notary public commissioned and qualified in and for said county, appeared Robert D. Proett, who is personally known by me to the identical person whose name is affixed above, and he did acknowledge the execution of the foregoing affidavit to be his voluntary act and deed.

Witness my hand and official seal on the date last aforesaid.

My commission expires



CASH 1706H BK 1053 R COMP FB MC-09030  
TYPE MISC PG 734 C/O COMP SCAN  
FEE 24.00 CF MISC 2561 PG 734 MC FV

RECEIVED  
JAN 12 1 00 PM '93  
REGISTER OF DEEDS  
DOUGLAS COUNTY, NE

Book \_\_\_\_\_ Page \_\_\_\_\_

Date Dec 24, 1992

Job Number 88008

\* NOTICE: ERROR HAS BEEN FOUND INASMUCH AS: NOTARIAL SEAL OR CORPORATE SEALS CANNOT BE AFFIXED OVER PRINTED MATTER. TOO LIGHT OR BLURRED NOTARIES ARE NOT ACCEPTED. COMMISSION EXPIRES MUST BE TYPED OUT.

REGISTER OF DEEDS.